## KING COUPTY INTERNATIONAL AIRPORT INC. 'NT REPORT

INCIDENT:	DATE OCCURRED	DATE REPORTED11-23-91
Fuel Spill	TIME OCCURRED	TIME REPORTED 1735
LOCATION(S) OF OCCURRENCE:		
Airport Fuel Farm		
REPORTED BY:	PHONE NO(S):	
Wings Aloft		
SUMMARY:		
at above location. Mos lineman that was fuelin and it was when he hear investigated finding fu	nk of water from FD2 on an approx t of the fuel went down drain at g their truck, John Benisch said d a noise coming from the right s el coming from the side by meter, to get fuel truck checked out be	fuel farm. The Wings Aloft the auto shutoff did not work, side of the truck and (overflow?).
cc: Ole Olsen		
OFFICERS: B C	·	